



PARTS SERVICE BULLETIN

A0-Z-28 R4

DATE: August 27, 2013

MODEL(S): All SCH Series

PAGE 1 OF 1

21433 SW Oregon Street, Sherwood, OR 97140 USA • Tel 503.625.2560 • Fax (Winch Dept) 503.625.7269 • Fax (Parts Dept) 503.625.5132

SUBJECT: Accumulator Kits for 327610W

The 327610W accumulator used in many Hyster/Allied Winch applications is **no longer available**. Consequently, Allied Systems Company has established service kits to replace the accumulator for the different winch models affected by this change.

Winch Model	Service Kit Part Number	Accumulator Only
W3A	2312814	2302110W
W3.5B	2307508W	2302110W
W3C	2307525W	2302110W
W5A, W5B	2307531W	2302110W
W5C	2314826	2302110W
W6F	2304704W	R16271
W6G	2304704W	R16271
W8L	2304704W	R16271
W12E (Power Controls)	2307509W	2302110W

Please refer to Figure 1 below to determine if your winch has already been updated.




Figure 1: Accumulators

NOTE: Once the 327610W accumulator has been updated with the appropriate service kit, customers will be able to service the replacement accumulator separately as referenced in the above table.

If there are any questions, please call the Allied Systems Company Service Parts Department at 503-625-2560.